Agency Index BK 20 PG 49 CORNER RECORD Document Number 20170071 City of \_\_\_\_\_\_ County of Placer \_\_\_\_\_ California MONUMENT AS SHOWN ON 22-RS-47, O.R.P.C. Brief Legal Descritption COORDINATES (OPTIONAL) **CORNER TYPE** \_\_\_\_\_ E. \_\_\_\_ Government Cor. Control SEC 33 Elevation Meander Property⊠ T13N Units ☐ Metric ☒ U.S. Survey Foot other  $\square$ R8E Rancho Horizontal Datum\_ \_\_Epoch Date\_\_\_ Zone Date of Survey NOVEMBER 21, 2017 Vertical Datum ☐ Complies with Public Resources code § 8801-8819 ☐ Complies with Public Resources code §8890-8902 ☐ Other PLS Act Ref: ☐ 8765(d) ⊠ 8771 8773 Established ☐ Pre-Construction ☐ Left as Found Corner/ Monument: ☐ Found and Tagged ☐ Reestablished ☐ Referenced Narrative of corner identified and monument as found. set, reset, replaced, or removed:  $\boxtimes$  See sheet # 2 for description(s): FOUND MONUMENT AS SHOWN, PER RECORD OF SURVEY NO. 3220, RECORDED IN BOOK 22 OF SURVEYS, PAGE 47, P.C.R., PRIOR TO NEW SIDEWALK CONSTRUCTION, TIED FOUND MONUMENT FROM REFERENCE POINTS ESTABLISHED FROM PROJECT CONTROL. REPLACED DESTROYED MONUMENT AFTER CONSTRUCTION. CORNER RECORDS, PAGE SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with the Professional Land Surveyors' Act on MARCH 21, 2018 Exp. 12-31-2019 P.L.S. or R.C.E. No. Signed No. 7941 COUNTY SURVEYOR'S STATEMENT This Corner Record was received and examined and filed Amric 3, 200 Signed Isoles Klime~ P.L.S. or R.C.E. No. <u>658</u>4 County Surveyor's Comment: Exp. 12-31-2019

No. 6584

OF CAL

